

# CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 13 November 2014 to 0901Z 8 January 2015

AERODROME/FACILITY DIRECTORY B287

## FAIRMONT HOT SPRINGS BC

CYXZ

<b>REF</b>	N50 19 49 W115 52 24 15°E (2013) UTC-7(6) Elev 2658' A5005 LO2 HI3 CAP RCAP	
<b>OPR</b>	Fairmont Hot Springs Resort 250-345-2121/6311 Fax 250-345-2162 APM 250-345-0180, 250-342-1664 Reg Ldg fees	
<b>PF</b>	B-1 C-2,5 D-3,4,6	
<b>FLT PLN</b>	NOTAM FILE CYXC	
<b>FIC</b>	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
<b>WX</b>	AUTO 250-345-6361 (see COMM)	
<b>SERVICES</b>		
<b>FUEL</b>	100LL, JA (with FSII), SP	
<b>OIL</b>	All	
<b>S</b>	4,5,6	
<b>RWY DATA</b>	Rwy 15(156°)/33(336°) 6004x100 asphalt Thld 33 displ 820'. Rwy 15 up 0.4%.	
<b>RCR</b>	Opr Ltd win maint	
<b>LIGHTING</b>	15-AS(TE LO) P2, 33-AS(TE LO) P2 PAPI Rwy 15 offset 12° rgt. ARCAL-123.2 type K. ARCAL opr A/D beacon.	
<b>COMM</b>		
<b>RCO</b>	Pacific rdo (Invermere) 123.475 (FISE) 126.7 (bcst)	
<b>ATF</b>	tfc 123.2 5NM 5700 ASL	
<b>AUTO</b>	122.975	
<b>NAV</b>		
<b>NDB</b>	D6 261 (L) N50 19 37 W115 52 36 Pvt	
<b>PRO</b>	Rgt hand circuits rwy 15 (CAR 602.96).	
<b>CAUTION</b>	Hwy overpass & p-line aprx 40 AGL crosses apch Rwy 33 aprx 1250' fr rwy thld. Extensive glider activity over mtns to E of A/D. Recommend only pilots familiar with lcl area use this aprt dur hrs of darkness. Ngt ops not recommended unless all 4 hazard beacons oprg. Extv bird activity in vic of rwy.	

